

“Holden Isuzu, Rodeo, Colorado, D-max Remote Key - Worn out button replacement procedure” was prepared by Polmex , the West Australian innovative Engineering Company, specializing in design and manufacture of special purpose Silicone products. Supplying to the market Silicone Replacement Buttons for worn remote keys of various car makes and models. Holden, Land Rover, Mitsubishi, Nissan, Hyundai, Toyota, Ford, Commodore, Mazda, BMW and more ...

For Orders please visit us on line at www.polmex.com.au

You are replacing 2 worn buttons in **Holden Rodeo, Colorado, Isuzu** key with Silicone Repair Pad from POLMEX.

Our pads are made form high purity LSR Silicone and will not: deform, change shape, become brittle and break unlike original cover. It is a great fix at a fraction of the price of new remote and re-programming.



Use flat screwdriver to prise remote open on the split line. You will end up with bottom part of shell and top shell with buttons and electronic board.



Remove electronic component from top shell and uncover thin rubber spacer.



Remove rubber spacer and existing worn buttons. With our flexible Silicone Pad, rubber spacer will not be need it.




Start installing new pad by pushing one end of it under cut-out in plastic shell, till it stays in place



Continue the same process for second cut-out till last section of the new replacement pad engages with plastic cover.



Push buttons slightly thru cut-outs till they look levelled with surface of the shell. Once Buttons pad is installed and buttons sit correctly, you can put your remote key together in reverse order.



Place electronic component on the top of the Silicone Pad taking care of the little light that should gently fit in the hole provided (*as highlighted above*).



Place bottom part of shell over the top part and close it till it clicks. Your refurbished remote is ready for use without need for re-programming.